Dutch Gap Canal
North Mill Creek Watershed
Water Quality

STORMWATER MANAGEMENT COMMISSION

This map is provided for general locational information only. Map features have been derived from various sources, each of which has its own scale and accuracy. The locations of all features are approximate.
Lake County Stormwater Management Commission
February 7, 2006
modified February 21, 2011

DATA SOURCES:
Kenosha County GIS
Lake County Stormwater Management
Southeastern Wisconsin Regional Planning Commission
Lake County Department of Information And Technology, GIS & Mapping Division



- State Boundary
- North Mill Creek Watershed
- 303(d) Listed Lakes
- 303(d) Listed Streams
- Highly Erodible Soils
- Lake Monitoring Sites
- Lindenhurst Sewage Treatment Plant
- Potential Problem Discharge Locations
- Stream Monitoring Stations
- Potential Septic Failures
- State Highways and Major Roads
- Streets

Bank Erosion (Creeks)

- None
- Low
- Moderate
- High
- Not Assessed

Shoreline Erosion (Lakes)

- None - 0%
- Low - 1% - 20%
- Moderate - 21% - 40%
- High - > 40%
- Not Assessed