

LC400203 FIBER GLASS FABRIC REPAIR SYSTEM (LCDOT) For use on LCDOT let projects only - do not include in IDOT let projects. Delete this note from the Contract Specifications.

Effective: January 1, 2007

Revised: May 19, 2014

Description: This work shall consist of the installation of a fiber glass fabric repair system prior to placement of a hot-mix asphalt overlay.

Materials: The materials shall meet the requirements of Section 1063 of the "Standard Specifications".

Equipment: The equipment shall meet the requirements of Article 444.03 of the "Standard Specifications".

General: The work shall be performed according to Section 444 of the "Standard Specifications", except that:

The material shall be 24 inches wide, and shall be applied to the joint between existing and widened pavement as shown on the plans.

Method of Measurement: This work will be measured in place and the overall length calculated in feet. No allowance will be made for fabric overlaps.

Basis of Payment: This work will be paid for at the contract unit price per foot for FIBER GLASS FABRIC REPAIR SYSTEM. *The unit price shall include all equipment, materials and labor required to furnish and install the fiber glass fabric repair system.*