



Eastern Research Group  
601 Keystone Park Drive  
Suite 700  
Morrisville, NC 27560

December 02, 2019

Mr. Benjamin Chandler  
GHD Services Inc.  
11719 Hinson Road, Suite 100  
Little Rock, AR 72223  
Project Name: Village of Gurnee

Dear Mr. Benjamin Chandler,

This report contains the analytical results for the sample(s) received under chain(s) of custody by Eastern Research Group on 11/06/19 10:20.

The test results in this report are in compliance with NELAC accreditation requirements for the certified parameters. All analyses were performed as described in the US EPA-approved QAPP, under the contract for UATMP, NATTS, CSATAM, PAMS and NMOC support (US EPA Contract No. EP-D-14-030). This cover page is an integral part of this report, and any exceptions or comments are noted on the last page.

Release of the data contained in this data package and in the data submitted in the electronic data deliverable, has been authorized by the Program Manager, or the Program Manager's designee as verified by the following signature.

The issuance of the final Certificate of Analysis takes precedence over any previous Report. If you have any questions, please contact me at 919-468-7924.

Sincerely,

Julie Swift  
Program Manager  
[julie.swift@erg.com](mailto:julie.swift@erg.com)

The information contained in this report and its attachment(s) are intended only for the use of the individual to whom it is addressed and may contain information that is privileged, confidential, or exempt from disclosure. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this report is strictly prohibited. If you have received this report in error, please notify [julie.swift@erg.com](mailto:julie.swift@erg.com) and delete the report without retaining any copies.



# CERTIFICATE OF ANALYSIS

GHD Services Inc.  
 11719 Hinson Road, Suite 100  
 Little Rock, AR 72223  
**ATTN:** Mr. Benjamin Chandler  
**PHONE:** (501) 224-1926 **FAX:**

**FILE #:** 4210.00  
**REPORTED:** 12/02/19 11:13  
**SUBMITTED:** 11/06/19  
**AQS SITE CODE:**  
**SITE CODE:** Village of Gurnee

## ANALYTICAL REPORT FOR SAMPLES

<u>SampleName</u>	<u>LabNumber</u>	<u>Matrix</u>	<u>Sampled</u>	<u>Received</u>
11197130-R1-04	9110634-01	Air	11/04/19 23:59	11/06/19 10:20
11197130-R2-04	9110634-02	Air	11/04/19 23:59	11/06/19 10:20
11197130-M1-04	9110634-03	Air	11/04/19 23:59	11/06/19 10:20
11197130-M2-04	9110634-04	Air	11/04/19 23:59	11/06/19 10:20
11197130-M3-04	9110634-05	Air	11/04/19 23:59	11/06/19 10:20
11197130-M4-04	9110634-06	Air	11/04/19 23:59	11/06/19 10:20
11197130-M5-04	9110634-07	Air	11/04/19 23:59	11/06/19 10:20
11197130-V1-04	9110634-08	Air	11/04/19 23:59	11/06/19 10:20
11197130-V2-04	9110634-09	Air	11/04/19 23:59	11/06/19 10:20
11197130-V3-04	9110634-10	Air	11/04/19 23:59	11/06/19 10:20
11197130-V4-04	9110634-11	Air	11/04/19 23:59	11/06/19 10:20
11197130-V5-04	9110634-12	Air	11/04/19 23:59	11/06/19 10:20



# CERTIFICATE OF ANALYSIS

GHD Services Inc.  
 11719 Hinson Road, Suite 100  
 Little Rock, AR 72223  
 ATTN: Mr. Benjamin Chandler  
 PHONE: (501) 224-1926 FAX:

FILE #: 4210.00  
 REPORTED: 12/02/19 11:13  
 SUBMITTED: 11/06/19  
 AQS SITE CODE:  
 SITE CODE: Village of Gurnee

---

<b>Description:</b> 11197130-R1-04	<b>Lab ID:</b> 9110634-01	<b>Sampled:</b> 11/04/19 23:59
<b>Pressure @ Receipt:</b> 6.50" Hg	<b>Canister #:</b> A21006	<b>Received:</b> 11/06/19 10:20
<b>Comments:</b>		<b>Analyzed:</b> 11/13/19 20:52

---

### Air Toxics by EPA Compendium Method TO-15

<u>Analyte</u>	<u>Results</u>		<u>Flag</u>	<u>MDL</u>
	<u>ppbv</u>	<u>ug/m<sup>3</sup></u>		<u>ppbv</u>
Ethylene oxide	0.0859	0.16		0.0250



# CERTIFICATE OF ANALYSIS

GHD Services Inc.  
 11719 Hinson Road, Suite 100  
 Little Rock, AR 72223  
 ATTN: Mr. Benjamin Chandler  
 PHONE: (501) 224-1926 FAX:

FILE #: 4210.00  
 REPORTED: 12/02/19 11:13  
 SUBMITTED: 11/06/19  
 AQS SITE CODE:  
 SITE CODE: Village of Gurnee

**Description:** 11197130-R2-04      **Lab ID:** 9110634-02      **Sampled:** 11/04/19 23:59  
**Pressure @ Receipt:** 7.50" Hg      **Canister #:** 5129      **Received:** 11/06/19 10:20  
**Comments:**      **Analyzed:** 11/13/19 21:40

### Air Toxics by EPA Compendium Method TO-15

<u>Analyte</u>	<u>Results</u>		<u>Flag</u>	<u>MDL</u>
	<u>ppbv</u>	<u>ug/m<sup>3</sup></u>		<u>ppbv</u>
Ethylene oxide	0.0628	0.11		0.0250



# CERTIFICATE OF ANALYSIS

GHD Services Inc.  
 11719 Hinson Road, Suite 100  
 Little Rock, AR 72223  
 ATTN: Mr. Benjamin Chandler  
 PHONE: (501) 224-1926 FAX:

FILE #: 4210.00  
 REPORTED: 12/02/19 11:13  
 SUBMITTED: 11/06/19  
 AQS SITE CODE:  
 SITE CODE: Village of Gurnee

**Description:** 11197130-M1-04      **Lab ID:** 9110634-03      **Sampled:** 11/04/19 23:59  
**Pressure @ Receipt:** 4.50" Hg      **Canister #:** SAT086      **Received:** 11/06/19 10:20  
**Comments:**      **Analyzed:** 11/13/19 22:29

### Air Toxics by EPA Compendium Method TO-15

<u>Analyte</u>	<u>Results</u>		<u>Flag</u>	<u>MDL</u>
	<u>ppbv</u>	<u>ug/m<sup>3</sup></u>		<u>ppbv</u>
Ethylene oxide	0.0872	0.16		0.0250



# CERTIFICATE OF ANALYSIS

GHD Services Inc.  
 11719 Hinson Road, Suite 100  
 Little Rock, AR 72223  
 ATTN: Mr. Benjamin Chandler  
 PHONE: (501) 224-1926 FAX:

FILE #: 4210.00  
 REPORTED: 12/02/19 11:13  
 SUBMITTED: 11/06/19  
 AQS SITE CODE:  
 SITE CODE: Village of Gurnee

---

<b>Description:</b> 11197130-M2-04	<b>Lab ID:</b> 9110634-04	<b>Sampled:</b> 11/04/19 23:59
<b>Pressure @ Receipt:</b> 5.00" Hg	<b>Canister #:</b> 18873	<b>Received:</b> 11/06/19 10:20
<b>Comments:</b>		<b>Analyzed:</b> 11/13/19 23:17

---

### Air Toxics by EPA Compendium Method TO-15

<u>Analyte</u>	<u>Results</u>		<u>Flag</u>	<u>MDL</u>
	<u>ppbv</u>	<u>ug/m<sup>3</sup></u>		<u>ppbv</u>
Ethylene oxide	ND	ND	U	0.0250



# CERTIFICATE OF ANALYSIS

GHD Services Inc.  
 11719 Hinson Road, Suite 100  
 Little Rock, AR 72223  
 ATTN: Mr. Benjamin Chandler  
 PHONE: (501) 224-1926 FAX:

FILE #: 4210.00  
 REPORTED: 12/02/19 11:13  
 SUBMITTED: 11/06/19  
 AQS SITE CODE:  
 SITE CODE: Village of Gurnee

---

<b>Description:</b> 11197130-M3-04	<b>Lab ID:</b> 9110634-05	<b>Sampled:</b> 11/04/19 23:59
<b>Pressure @ Receipt:</b> 5.50" Hg	<b>Canister #:</b> A21097	<b>Received:</b> 11/06/19 10:20
<b>Comments:</b>		<b>Analyzed:</b> 11/14/19 00:06

---

### Air Toxics by EPA Compendium Method TO-15

<u>Analyte</u>	<u>Results</u>		<u>Flag</u>	<u>MDL</u>
	<u>ppbv</u>	<u>ug/m<sup>3</sup></u>		<u>ppbv</u>
Ethylene oxide	0.0525	0.09		0.0250



# CERTIFICATE OF ANALYSIS

GHD Services Inc.  
 11719 Hinson Road, Suite 100  
 Little Rock, AR 72223  
 ATTN: Mr. Benjamin Chandler  
 PHONE: (501) 224-1926 FAX:

FILE #: 4210.00  
 REPORTED: 12/02/19 11:13  
 SUBMITTED: 11/06/19  
 AQS SITE CODE:  
 SITE CODE: Village of Gurnee

---

<b>Description:</b> 11197130-M4-04	<b>Lab ID:</b> 9110634-06	<b>Sampled:</b> 11/04/19 23:59
<b>Pressure @ Receipt:</b> 6.00" Hg	<b>Canister #:</b> SAT165	<b>Received:</b> 11/06/19 10:20
<b>Comments:</b>		<b>Analyzed:</b> 11/14/19 00:54

---

### Air Toxics by EPA Compendium Method TO-15

<u>Analyte</u>	<u>Results</u>		<u>Flag</u>	<u>MDL</u>
	<u>ppbv</u>	<u>ug/m<sup>3</sup></u>		<u>ppbv</u>
Ethylene oxide	0.388	0.70		0.0250



# CERTIFICATE OF ANALYSIS

GHD Services Inc.  
 11719 Hinson Road, Suite 100  
 Little Rock, AR 72223  
**ATTN:** Mr. Benjamin Chandler  
**PHONE:** (501) 224-1926 **FAX:**

**FILE #:** 4210.00  
**REPORTED:** 12/02/19 11:13  
**SUBMITTED:** 11/06/19  
**AQS SITE CODE:**  
**SITE CODE:** Village of Gurnee

**Description:** 11197130-M5-04      **Lab ID:** 9110634-07      **Sampled:** 11/04/19 23:59  
**Pressure @ Receipt:** 6.50" Hg      **Canister #:** SAT049      **Received:** 11/06/19 10:20  
**Comments:**      **Analyzed:** 11/14/19 01:42

### Air Toxics by EPA Compendium Method TO-15

<u>Analyte</u>	<u>Results</u>		<u>Flag</u>	<u>MDL</u>
	<u>ppbv</u>	<u>ug/m<sup>3</sup></u>		<u>ppbv</u>
Ethylene oxide	ND	ND	U	0.0250



# CERTIFICATE OF ANALYSIS

GHD Services Inc.  
 11719 Hinson Road, Suite 100  
 Little Rock, AR 72223  
 ATTN: Mr. Benjamin Chandler  
 PHONE: (501) 224-1926 FAX:

FILE #: 4210.00  
 REPORTED: 12/02/19 11:13  
 SUBMITTED: 11/06/19  
 AQS SITE CODE:  
 SITE CODE: Village of Gurnee

---

<b>Description:</b> 11197130-V1-04	<b>Lab ID:</b> 9110634-08	<b>Sampled:</b> 11/04/19 23:59
<b>Pressure @ Receipt:</b> 5.50" Hg	<b>Canister #:</b> SAT054	<b>Received:</b> 11/06/19 10:20
<b>Comments:</b>		<b>Analyzed:</b> 11/14/19 02:31

---

### Air Toxics by EPA Compendium Method TO-15

<u>Analyte</u>	<u>Results</u>		<u>Flag</u>	<u>MDL</u>
	<u>ppbv</u>	<u>ug/m<sup>3</sup></u>		<u>ppbv</u>
Ethylene oxide	0.0601	0.11	U	0.0250



# CERTIFICATE OF ANALYSIS

GHD Services Inc.  
 11719 Hinson Road, Suite 100  
 Little Rock, AR 72223  
 ATTN: Mr. Benjamin Chandler  
 PHONE: (501) 224-1926 FAX:

FILE #: 4210.00  
 REPORTED: 12/02/19 11:13  
 SUBMITTED: 11/06/19  
 AQS SITE CODE:  
 SITE CODE: Village of Gurnee

---

<b>Description:</b> 11197130-V2-04	<b>Lab ID:</b> 9110634-09	<b>Sampled:</b> 11/04/19 23:59
<b>Pressure @ Receipt:</b> 7.50" Hg	<b>Canister #:</b> SAT026	<b>Received:</b> 11/06/19 10:20
<b>Comments:</b>		<b>Analyzed:</b> 11/14/19 03:19

---

### Air Toxics by EPA Compendium Method TO-15

<u>Analyte</u>	<u>Results</u>		<u>Flag</u>	<u>MDL</u>
	<u>ppbv</u>	<u>ug/m<sup>3</sup></u>		<u>ppbv</u>
Ethylene oxide	0.743	1.34		0.0250



# CERTIFICATE OF ANALYSIS

GHD Services Inc.  
 11719 Hinson Road, Suite 100  
 Little Rock, AR 72223  
 ATTN: Mr. Benjamin Chandler  
 PHONE: (501) 224-1926 FAX:

FILE #: 4210.00  
 REPORTED: 12/02/19 11:13  
 SUBMITTED: 11/06/19  
 AQS SITE CODE:  
 SITE CODE: Village of Gurnee

**Description:** 11197130-V3-04      **Lab ID:** 9110634-10      **Sampled:** 11/04/19 23:59  
**Pressure @ Receipt:** 7.00" Hg      **Canister #:** 5045      **Received:** 11/06/19 10:20  
**Comments:**      **Analyzed:** 11/14/19 16:51

## Air Toxics by EPA Compendium Method TO-15

<u>Analyte</u>	<u>Results</u>		<u>Flag</u>	<u>MDL</u>
	<u>ppbv</u>	<u>ug/m<sup>3</sup></u>		<u>ppbv</u>
Ethylene oxide	0.123	0.22		0.0250



# CERTIFICATE OF ANALYSIS

GHD Services Inc.  
 11719 Hinson Road, Suite 100  
 Little Rock, AR 72223  
 ATTN: Mr. Benjamin Chandler  
 PHONE: (501) 224-1926 FAX:

FILE #: 4210.00  
 REPORTED: 12/02/19 11:13  
 SUBMITTED: 11/06/19  
 AQS SITE CODE:  
 SITE CODE: Village of Gurnee

---

<b>Description:</b> 11197130-V4-04	<b>Lab ID:</b> 9110634-11	<b>Sampled:</b> 11/04/19 23:59
<b>Pressure @ Receipt:</b> 6.50" Hg	<b>Canister #:</b> A21007	<b>Received:</b> 11/06/19 10:20
<b>Comments:</b>		<b>Analyzed:</b> 11/14/19 17:40

---

### Air Toxics by EPA Compendium Method TO-15

<u>Analyte</u>	<u>Results</u>		<u>Flag</u>	<u>MDL</u>
	<u>ppbv</u>	<u>ug/m<sup>3</sup></u>		<u>ppbv</u>
Ethylene oxide	0.0308	0.06		0.0250



# CERTIFICATE OF ANALYSIS

GHD Services Inc.  
 11719 Hinson Road, Suite 100  
 Little Rock, AR 72223  
 ATTN: Mr. Benjamin Chandler  
 PHONE: (501) 224-1926 FAX:

FILE #: 4210.00  
 REPORTED: 12/02/19 11:13  
 SUBMITTED: 11/06/19  
 AQS SITE CODE:  
 SITE CODE: Village of Gurnee

---

<b>Description:</b> 11197130-V5-04	<b>Lab ID:</b> 9110634-12	<b>Sampled:</b> 11/04/19 23:59
<b>Pressure @ Receipt:</b> 5.50" Hg	<b>Canister #:</b> SAT032	<b>Received:</b> 11/06/19 10:20
<b>Comments:</b>		<b>Analyzed:</b> 11/14/19 18:28

---

### Air Toxics by EPA Compendium Method TO-15

<u>Analyte</u>	<u>Results</u>		<u>Flag</u>	<u>MDL</u>
	<u>ppbv</u>	<u>ug/m<sup>3</sup></u>		<u>ppbv</u>
Ethylene oxide	0.111	0.20		0.0250



# CERTIFICATE OF ANALYSIS

GHD Services Inc.  
 11719 Hinson Road, Suite 100  
 Little Rock, AR 72223  
**ATTN:** Mr. Benjamin Chandler  
**PHONE:** (501) 224-1926 **FAX:**

**FILE #:** 4210.00  
**REPORTED:** 12/02/19 11:13  
**SUBMITTED:** 11/06/19  
**AQS SITE CODE:**  
**SITE CODE:** Village of Gurnee

Analyte	Result	Units	Source Result	RPD	RPD Limit	Notes
---------	--------	-------	---------------	-----	-----------	-------

## Air Toxics by EPA Compendium Method TO-15 - Quality Control

*Batch B9K1306 - Summa Canister Prep*

**Blank (B9K1306-BLK1)**

Prepared: 10/21/19 Analyzed: 11/13/19

Ethylene oxide	ND	ppbv				U
----------------	----	------	--	--	--	---

**Duplicate (B9K1306-DUP1)**

**Source: 9110634-09**

Prepared: 11/04/19 Analyzed: 11/15/19

Ethylene oxide	0.735	ppbv	0.74	1.16	25	
----------------	-------	------	------	------	----	--

*Batch B9K1401 - Summa Canister Prep*

**Blank (B9K1401-BLK1)**

Prepared: 11/12/19 Analyzed: 11/14/19

Ethylene oxide	ND	ppbv				U
----------------	----	------	--	--	--	---



# CERTIFICATE OF ANALYSIS

GHD Services Inc.  
 11719 Hinson Road, Suite 100  
 Little Rock, AR 72223  
**ATTN:** Mr. Benjamin Chandler  
**PHONE:** (501) 224-1926 **FAX:**

**FILE #:** 4210.00  
**REPORTED:** 12/02/19 11:13  
**SUBMITTED:** 11/06/19  
**AQS SITE CODE:**  
**SITE CODE:** Village of Gurnee

Analyte	Result	Units	% Difference	Limit (%)	Notes
---------	--------	-------	--------------	-----------	-------

## Air Toxics by EPA Compendium Method TO-15 - Quality Control

### Sequence 1911025

#### Calibration Check (1911025-CCV1)

Prepared & Analyzed: 11/13/19

Ethylene oxide	1.94	ppbv	-22.5	30.00	
----------------	------	------	-------	-------	--

### Sequence 1911027

#### Calibration Check (1911027-CCV1)

Prepared & Analyzed: 11/14/19

Ethylene oxide	1.87	ppbv	-25.3	30.00	
----------------	------	------	-------	-------	--



# CERTIFICATE OF ANALYSIS

GHD Services Inc.  
11719 Hinson Road, Suite 100  
Little Rock, AR 72223  
**ATTN:** Mr. Benjamin Chandler  
**PHONE:** (501) 224-1926 **FAX:**

**FILE #:** 4210.00  
**REPORTED:** 12/02/19 11:13  
**SUBMITTED:** 11/06/19  
**AQS SITE CODE:**  
**SITE CODE:** Village of Gurnee

## Notes and Definitions

U Under Detection Limit  
ND Analyte NOT DETECTED  
NR Not Reported  
MDL Method Detection Limit  
RPD Relative Percent Difference

Note: The test results meet all requirements of NELAC; however the following analytes are not accredited: 1,2,4-trimethylbenzene, 1,2-dibromoethane, 1,2-dichloropropane, 1,3,5-trimethylbenzene, 1,3-butadiene, acetylene, acrolein, bromochloromethane, bromodichloromethane, bromoform, carbon disulfide, dibromochloromethane, dichlorodifluoromethane, dichlorotetrafluoroethane, ethyl acrylate, ethyl tert butyl ether, ethylene oxide, hexachloro-1,3-butadiene, n-octane, propylene, tert amyl methyl ether, tetrachloroethylene, trans-1,2-dichloroethylene, trichlorofluoromethane, and trichlorotrifluoroethane.